

City of Centralia Rock Street Alley Bridge



***Flow Near Max. 6" to 8" Below
Superstructure***

City of Centralia Rock Street Alley Bridge



Deck View Facing West

City of Centralia Rock Street Alley Bridge



Deck View Facing East

Whatcom County Middle Fork Bridge



Elevation View

Whatcom County Middle Fork Bridge



Deck View

Whatcom County Middle Fork Bridge



***Cracked and Spalling Asphalt
Wearing Surface***

Whatcom County Middle Fork Bridge



***Beam Deterioration and Loose
Sidewalk Bolts***

Whatcom County Middle Fork Bridge



Laminar Rust at Steel Beam

Whatcom County Middle Fork Bridge



Typical Corrosion at Floorbeams

Snohomish Co Granite Falls



Elevation View

Snohomish Co Granite Falls



Deck View

Snohomish Co Granite Falls



***Joint Tight - No Room for
Expansion***

Snohomish Co Granite Falls



***Concrete Spalling over Floor
Beam***

Snohomish Co Granite Falls



Misaligned Rivets

Snohomish Co Granite Falls



Exposed Rusty Reinforcing Steel

King County Ames Lake Trestle



Elevation View

King County Ames Lake Trestle



Deck View

King County Ames Lake Trestle



Deck Maintenance in 1998

King County Ames Lake Trestle



Current Deck Condition

City of Sumner Stuck River Bridge



Elevation View

City of Sumner Stuck River Bridge



Deck View

City of Sumner Stuck River Bridge



Repaired Tension Members

City of Sumner Stuck River Bridge



Bent Sway Bracing

City of Sumner Stuck River



View Pier Wall and Underside of Bridge

City of Sumner Stuck River Bridge



Section Loss at Bottom Plate

Adams County Leo Dyck Bridge



Elevation View

Adams County Leo Dyck Bridge



Deck View with Load Posting

Adams County Rooster Bridge



Elevation View

Adams County Rooster Bridge



Elevation View

Adams County Rooster Bridge



Deck View

Adams County Rooster Bridge



Deck View

City of Chelan - Chelan River Bridge



Elevation View

City of Chelan - Chelan River Bridge



Deck View

City of Chelan - Chelan River Bridge



View of Deterioration at Soffit

City of Chelan - Chelan River Bridge



View of Spalling Concrete at Pier



***City of Chelan
Chelan River
Bridge***

***View of
Shift in
Barrier***

City of Chelan - Chelan River Bridge



View Showing Movement of Barrier

City of Sumner Fryar Bridge



Elevation View

City of Sumner Fryar Bridge



Deck View



***City of Sumner
Fryar Bridge***

***View of Failing
Abutment Wall***



***City of Sumner
Fryar Bridge***

***Spalling of
Abutment
Wall***



***City of Sumner
Fryar Bridge***

***View of Bridge
Railing***

Pierce County Tacoma Eastern RR Bridge



Elevation View

Pierce County Tacoma Eastern RR Bridge



Deck View Facing West